

Suspend/Resume ECO Checklist

S/N:

MAC:

Model:

Circuit/Component Changes	Side	Done	Comments
Added CPU Supervisor			
Removed C56 and R43			
Changed R20 to 33K	top		
Changed R22 to 32.37K	top		
Added 0.1 uF to Q49, 2	top		
Added 4.7 uF to R141	top		
Cut trace under U48	top		
Add 4.7K and 0.1 uF to U48	top		
Change Q1 to AO3420	top		
Change R231 to 33K	top		
Add 2.2K across C157	top		
SDRAM			
Add a 0.001 uF cap to C255	top		
" (X7R) C303	top		
" C283	top		
" C334	top		
+3.3V			
" C266	top		
" C249	top		
" C575	top		
" C80			
" C68			
" C50			
" C48			
" C58			
" C391			
USB			
Add a 0.001 uF cap to C81			
" C82			
WLAN Caps			
" C591			
" C592			
DCON			
" C374			
" C376			
" C396			
" C579			
" C387			
" C388			
" C384			
" C380	top		
" C400	top		