



Activity

Browse

View

RESCO REMOTE

[Manual](#)

Search

Abamakoro Ltd (UT00001)

- Abaua Kauriri 9.0 (UT00030)
- Abiete Bureniti 3.0 (UT00373)
- Airin Bwereata (UT00011)
- Aitiria Tamton 9.0 (UT00049)
- Aito Kabuati 21.0 (UT00173)
- Amoange Pri Scl 1 Nanoua 5.0 (UT00382)
- Amoange Pri Scl 2 Mwaneaba 5.0 (UT00383)
- Amoange Pri Scl 3 Kiaua 4.0 (UT00384)
- Amoange Pri Scl 4 Wendy Tiiti 7.0 (UT00385)
- Amoange Pri Scl 5 Taboree 5.0 (UT00386)
- Angiteiti Kabwebwenibeia 7.0 (UT00024)
- Anterea Buraniko 5.0 (UT00006)
- Antonio Maria 13.0 (UT00036)
- Antonio Temwake (UT00370)
- Arebonto Tibure 6.0 (UT00067)
- Ariraoi Maneaba 6.0 (UT00183)
- Ariraoi Mwaneaba KPC Teaeinibai (UT03152)
- Arobati Miriam (UT00380)
- Arobati Tio 6.0 (UT00218)
- Assembly of God 4.0 (UT00003)
- Ataieta Beeta 5.0 (UT00007)
- Atanimakin Makin 10.0

UT00001 - ABAMAKORO LTD

Nooto (North Tarawa)

STATUS	TARIFF	MONTHS IN ARREAR	COMISSIONED DATE
Active	Basic +1 Change Tariff	0.1 \$1.0.-	Jan 01, 2003

[Set Yellow Card](#)



Invoicing

Monitoring

PV System

[+ Add new Monitoring information](#)

	Date	Weather	Day before	User	Signed	Alarms	Description
	Jun 07, 2005						650.0ml. of water was added. Electrolyte Level was Low level.
	May 23, 2005						Electrolyte Level was Maximum Level.
	Apr						300.0ml. of water was